



**SECTION A-A**

SECTION WHERE UNSUITABLE MATERIAL IS PRESENT



**SECTION B-B**

SECTION IN LEDGE



- SUBSIDIARY EXCAVATION (0-9')
- COMMON STRUCTURE EXCAVATION
- SEE SPEC. 209.2.1
- ROCK STRUCTURE EXCAVATION